

# Vision Protect Professional Application Instructions for Nanovations USA Glass Treatment

## DESCRIPTION

Vision Protect is an effective hydrophobic treatment that offers protection for all glass surfaces.

## SURFACE PREPARATION

First remove all dirt, grime, and loose particles, and clean the glass prior to using, the **CL-50** surface preparation chemical. Always start the cleaning process at the top of the glass, and work down to the bottom. Proceed to clean the glass surface by spraying a small amount of the **CL-50** solution onto the glass surface in a specific area. Then, using the provided **red cloth**, commence a spray and wipe process while cleaning and polishing the surface with overlapping circular motions. If the ambient air is hot during the application, a small amount of water may be added to the surface to assist in the surface preparation. Continue until the surface is crystal clear and streak free. The **red cloth** may be used more than once if still "clean".

Wipe all frames, edges and seals after the cleaning. The **blue micro-fiber towel** or paper towel may be used. Make sure all water from these areas is removed and the perimeter is dry.

## COATING APPLICATION

On a glass surface that is properly cleaned and completely dry, it is time to complete the process. Spray on a small amount of the **NG 1010** Glass Coating technology to a specific area, then, using the provided **white cloth**, commence the application process using circular, overlapping motions, making sure to cover the complete surface.

*Apply the product as thin as possible over the complete surface being treated, while making sure the next area overlaps, ensuring complete coverage of the area being treated.*

There should be no visible residue after you finish the coating process. Finish with a final polish using the **white cloth**, without any product present. The **white cloth** may be reused if it has not been soiled.

## CURING

Rainproof after 15 minutes. Reaches maximum hardness and optimal repellent effect after 24 hours. For performance testing allow curing for 24 hours.

## STORAGE & HANDLING

**Application temperature:** For optimal results the application area should be 36°-86°F / 4°-35°C during preparation, application and initial curing.

The glass coating can be stored in tightly sealed original containers for at least 24 months, if kept dry and at moderate temperatures. It is important to reseal containers tightly after use. Store in a cool, dry place and protect from heat, freezing and direct sunlight. Containers with liquid product should be taken to a collection point for paint disposal.

## PRECAUTIONS

Keep out of reach of children. Product is an irritant to eyes. Rinse immediately with clean water if product comes in contact with eyes.

The coating product contains alcohol. Apply in well ventilated areas only. Close bottle after use and store in cool area.

**For SDS Info contact:**  
**Infotrac Acct# 101914**  
**24 Hour Emergency Phone:**  
**800-535-5053**  
**Int'l Emergency Phone:**  
**352-323-3500**